


Work Order ID 106460

September-03-13

Page 1

Item ID:	Revision ID:		
Item Name:			
Draw Nbr:	Start Date: 9/03/13 8:35:	Start Qty: 1.0000	
Revision Nbr:	Required Date: 9/03/13 8:35:	Reqd Qty: 1.0000	
Reference: ECN13-522	Cust Item ID:	Customer ID:	
Description: ADD PAPERWORK TO KITS IN STK (P107) FAA STC SH4786NM DATED 12-11-08, TC STC SH93-73 ISSUE 4	Sales Order:		

Approvals:	Process Plan: 	Date: _____	Tooling: _____	Date: _____
	QC: _____	Date: _____	SPC (Y/N): _____	Date: _____

		Hours		Tool ID	Tool #	Plan	Accept	Reject	Reject	Insp.
Sequence	Work Center	Operation	Set Up	Run						

9/3/13 (2)

QC21- 13/9/6

13-09-03

